

CA DEPT	DELIVERY LOCATION	TANK(S) SIZE	TANK LOCATION	TANK FITTING	TYPE OF FUEL	DIFFERENTIAL (\$0.0000)
CDC	Owens Valley CC #26 2781 South Round Valley Road Bishop	500	Above	Camlock	Gasoline	\$0.1600
CDF	Owens Valley CC 2781 South Round Valley Road Bishop	1000	Above	Camlock	Gasoline	\$0.1600
CDF	Owens Valley CC 2781 South Round Valley Road Bishop	2000	Above	Camlock	Diesel #2	\$0.1750
CDF	Owens Valley CC 2781 South Round Valley Road Bishop	2000	Above	Camlock	Diesel #2 Ultra Low Sulfur	\$0.1750
CDF	Owens Valley CC 2781 South Round Valley Road Bishop (Winterized Nov-Mar)	2000	Above	Camlock	Diesel #2	\$0.1750
CDF	Owens Valley CC 2781 South Round Valley Road Bishop (Winterized Nov-Mar)	2000	Above	Camlock	Diesel #2 Ultra Low Sulfur	\$0.1750
DOT	Bishop Maintenance Station 1250 Spruce Street Bishop	10000	Below		Diesel #2	\$0.1750
DOT	Bishop Maintenance Station 1250 Spruce Street Bishop	10000	Below		Diesel #2 Ultra Low Sulfur	\$0.1750
DOT	Bishop Maintenance Station 1250 Spruce Street Bishop (Winterized from Nov-Mar)	10000	Below		Diesel #2	\$0.1750
DOT	Bishop Maintenance Station 1250 Spruce Street Bishop (Winterized from Nov-Mar)	10000	Below		Diesel #2 Ultra Low Sulfur	\$0.1750
DOT	Death Valley Maintenance Sta State Route 190 2.5 Mile East of Furnace Creek Death Valley	10000	Above	4" Dry Valve	Diesel #2	\$0.1550
DOT	Death Valley Maintenance Sta State Route 190 2.5 Mile East of Furnace Creek Death Valley	10000	Above	4" Dry Valve	Diesel #2 Ultra Low Sulfur	\$0.1690
DOT	District Office 500 South Main Street Bishop	12500	Above	Camlock	Diesel #2	\$0.1390

DOT	District Office 500 South Main Street Bishop	12500	Above	Camlock	Diesel #2 Ultra Low Sulfur	\$0.1490
DOT	Independence Maintenance Sta 665 North Edwards Street Independence	4000	Above	Bottom Fill Scully Quick Connector	Diesel #2	\$0.1390
DOT	Independence Maintenance Sta 665 North Edwards Street Independence	4000	Above	Bottom Fill Scully Quick Connector	Diesel #2 Ultra Low Sulfur	\$0.1390
DOT	McGee Creek Crew Maint Sta Highway 395 35 Miles North of Bishop Bishop	8000	Above	Bottom Fill	Diesel #2	\$0.1600
DOT	McGee Creek Crew Maint Sta Highway 395 35 Miles North of Bishop Bishop	8000	Above	Bottom Fill	Diesel #2 Ultra Low Sulfur	\$0.1600
DOT	McGee Creek Crew Maint Sta Highway 395 35 Miles North of Bishop Bishop (Winterized from Nov-Mar)	8000	Above	Bottom Fill	Diesel #2	\$0.1600
DOT	McGee Creek Crew Maint Sta Highway 395 35 Miles North of Bishop Bishop (Winterized from Nov-Mar)	8000	Above	Bottom Fill	Diesel #2 Ultra Low Sulfur	\$0.1600
DOT	Shoshone Maintenance Station Junction of Routes 127 & 178 Shoshone	8000	Below		Diesel #2	\$0.1950
DOT	Shoshone Maintenance Station Junction of Routes 127 & 178 Shoshone	8000	Below		Diesel #2 Ultra Low Sulfur	\$0.1950